

HomeAir Hepa Empirical Study

Product: HomeAir Air Neutralizer

Location: Master bedroom with air conditioning

Date: January to end of April 2008

Conditions:

New- when the HEPA in new condition it supposed to be in white color

1 month – the HEPA filter has changed to grey color

4 months –the HEPA filter became dark grey and is about time to replace with a new HEPA Filter.

(Please refers to the replacement indicator at the side of HEPA Filter – as below picture)



New 1 month 4 months
ENVIPRO HomeAir HEPA condition



HomeAir



The HEPA Replacement Indicator will serve as

A HEPA filter replacement guide (From left to right)

Conclusion of finding:

The 4 months HEPA condition has proved that the HomeAir HEPA filter is capable to remove the dust particles up to 0.03 micron. The house owner has agreed the effectiveness of HEPA function.

Customer Testimonial:

My Name is John and Patty, we have been suffered for Sinus for many years, lately I have adopted HOMEAIR Air Neutralizer with HEPA & IONS, seem my Sinus has improved tremendously , sleep well and particularly not felt so much laziness and fatigue when wake up in the morning. After seeing the HEPA Conditions, I believe the effects of dust particles get into my lung over the years. Thank you ENVIPRO.

ENVIPRO – A product trademark for your health threats protection

Bring you the ***PUREST INDOOR AIR***.....

www.envipro.com.my

STH Research & Information Center

Dated: 7th May 2008